

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	3513-01
Description	AVIATION
Model	PC-1
Stock No.	26-3513 Version 1.0
Date	Sept. 13, 1982
Page 1 of	1

Problem

Wind direction calculated incorrectly.

* * THE FOLLOWING LINE CHANGES ARE REQUIRED! * *

Solution

The problem is corrected by following the steps listed below.

1. In BASIC, load the program by typing CLOAD"AVPACKI".
2. Make the following corrections:

* * * NOTE * * * Replace incorrect equations in lines 24 and 25. Change line 25 FIRST to release enough memory for changes to line 24.

CHANGES (Retype the line or refer to the Edit section of the owners manual)

Old Line: 25 IF I <> 0 * W <> 0 LET I = $\sqrt{I^2 + W^2}$: J = ASN(W/I) * SGN(Z-U):
J = 0 + J + 180 * (U > Z)

New Line: 25 J = J + 180 + 180 * (B < 0) + X

Old Line: 24 W = X - 0: J = 0: I = Z * COS W - U: W = Z * SIN W

New Line: 24 W = 0 - X: B = U * COS W - Z: G = U * SIN W: I = $\sqrt{BB + GG}$:
J = 0: IF B <> 0 LET J = ATN(G/B)

4. Type CSAVE"AVPACKI" to save the changes in the program to a new tape..
5. Make a backup copy of the corrected tape.