CUSTOMER SERVICE BULLETIN

Radio Shack®

CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4714-Ø2
Description	REFORMATTER
Model	Model II/16
Stock No.	26-4714 Ver.Ø1.Ø5.ØØ
Date	November 28, 1982
Page 1 of	1

Problem

Not all records are transferred on a TRANSFER ->IBM=>TRSDOS.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

To correct bad disk problem, apply the following patch:

```
PATCH REFM A=4947 F=2A C=24
```

To correct version number from Ø1.Ø5.ØØ to Ø1.5b.ØØ, apply the following patch:

```
PATCH REFM A=2AØ1 F=2Ø C=62
```

The following patches ARE REQUIRED for use on the Model 16. Do not apply for Model II use.

```
PATCH REFM A=5695 F=36ØØE1 C=C3CØ28
PATCH REFM A=28CØ F=ØØØØØØØØØØØØØØØØØØØØ C=36ØØE1CB7FC8E52E14C5
PATCH REFM A=28CA F=ØØØØØØØØØØØØØØØØØØØØ C=Ø1EØ2ECDB856C1DBE5D3
PATCH REFM A=28D4 F=ØØØØØØØØØØØØØØØØØØØØ C=E73E1BD3E4E3E3DBEØCB
PATCH REFM A=28DE F=ØØØØØØØØØØØØØØØØØØØØ C=4728FADBE4CB7F28Ø32D
PATCH REFM A=28E8 F=ØØØØØØØØØØØØØØØØ C=2ØDFCB87CBD7E1C9
```