CUSTOMER SERVICE BULLETIN

Problem

The patches listed below will permanently change HOST to function from channel B instead of channel A. These patches should not be applied unless one has a special situation which requires the use of the HOST function on channel B. Please note that a serial printer (which uses channel B) may not be used concurrently with HOST once these patches have been applied.

* * *   THESE PATCHES ARE OPTIONAL!   * * *

Solution

```
PATCH SYSTEM/SYS {R=11Ø B=2Ø4 F=6Ø6164 C=626365}
PATCH SYSTEM/SYS {R=64 B=164 F=41 C=42}
PATCH SYSTEM/SYS {R=64 B=173 F=CB5E28E1CB9EØ66Ø C=CB5628E1CB96Ø662}
PATCH SYSTEM/SYS {R=64 B=191 F=64 C=65}
PATCH SYSTEM/SYS {R=64 B=198 F=42 C=41}
PATCH SYSTEM/SYS {R=64 B=2Ø1 F=CB5628C5CB96Ø662 C=CB5E28C5CB9EØ66Ø}
PATCH SYSTEM/SYS {R=64 B=219 F=65 C=64}
```