CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4554-4
Description	ARS Series I
Model	Model II
Stock No.	26-4554 Version 1.1
Date	March 25, 1980
Page 1 of	1

Problem

If at MAIN Menu, option 1Ø is chosen and system initialization is exited back to MAIN MENU, Basic ERROR CODE 8 in line 51Ø6Ø is encountered. Pressing ENTER will continue execution of the program. It is not a fatal error.

Solution

The problem is corrected by following the steps listed below.

1. Backup the diskette(s) and make the changes on the Backup copy of the program.
2. In BASIC load the program by typing LOAD"ARSI/BAS".
3. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

Old Line: 51Ø6Ø IFR$<7"END"THEN RETURN ELSE GOTO 48Ø1Ø

New Line: 51Ø6Ø IFR$<7"END"THEN RETURN ELSE GOTO 48ØØØ

4. Type SAVE"ARSI/BAS" to save the changes in the program.
5. At TRSDOS Ready, make a backup copy of the corrected diskette.