CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	61Ø5-Ø9
Description	TRSDOS 16
Model	Model II/16
Stock No.	26-61Ø5 Version 4.1
Date	September 3Ø, 1982
Page 1 of	1

Problem

The distribution version of the SAVE utility on TRSDOS 4.1 does not properly handle diskettes with flawed sectors. Upon reaching a flawed sector, the program performs an infinite number of attempts to write to that sector.

The following patch corrects the situation to allow the SAVE utility to handle flawed diskettes.

* *   THE FOLLOWING PATCH IS REQUIRED!   * *

Solution

1.   At TRSDOS Ready, apply the following patch.

PATCH SAVE R=18 B=119 F=CDCF39DD36Ø1Ø2C5 C=C5CDCF39DD36Ø1Ø2

2.   Make a backup copy of the corrected diskette.