

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	<u>1063-1</u>
Description	<u>TRSDOS Manual</u>
Model	<u>Model III</u>
Stock No.	<u>26-1063 Version 1.2</u>
Date	<u>February 9, 1981</u>
Page 1 of	<u>1</u>

Problem

The terminal program (page 102 of the TRSDOS manual) won't output a character—it echoes back to screen but not thru telephone lines to the host computer.

Solution

On page 102, line 65 of the program should be changed from the old line to the new line.

Old Line: 65 DEFUSR2=&H0050

New Line: 65 DEFUSR2=&H0055_