

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	<u>1592-01</u>
Description	<u>PROFILE III PLUS</u>
Model	<u>Model III</u>
Stock No.	<u>26-1592 Vers. 01.00.00</u>
Date	<u>April 13, 1983</u>
Page 1 of	<u>1</u>

Problem

When asking for an addition or subtraction field, the system gives a field length of 1 less space than requested. For example, if you designate an addition field of 6 spaces, only 5 spaces are allowed in the field.

Solution

This is for your information. The program is working correctly. The restriction protects field overflow.