

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4150-06
Description	TRSDOS-II
Model	Model II
Stock No.	26-4150 Version 4.1
Date	July 22, 1982
Page 1 of	1

Problem

When an "INIT dr#" is performed on a floppy disk drive, not all records from the previously inserted diskette are cleared from the system. This problem will manifest itself when a "DIR" is done on one diskette containing two to eight files and then an "INIT" is done followed by the insertion of another diskette into the drive. A "DIR" on the new diskette will now show to have not only its files, but also some files from the first diskette.

* * * THESE PATCHES ARE REQUIRED. * * *

Solution

The following "PATCH" sequence will remedy this situation.

```
PATCH SYSRES/SYS {R=15 B=88 F=203BC5 C=C52039}  
PATCH SYSRES/SYS {R=15 B=99 F=29 C=2A}  
PATCH SYSRES/SYS {R=15 B=108 F=0911980E C=03C3981D}  
PATCH SYSRES/SYS {R=30 B=37 F=0000000000000000 C=D511980EEDA0EDA8}  
PATCH SYSRES/SYS {R=30 B=45 F=0000000000000000 C=4E23462BC37A0E}  
PATCH SYSRES/SYS {R=15 B=116 F=1814EDA0EDA8 C=4E23462BD500}  
PATCH SYSRES/SYS {R=15 B=141 F=E5 C=D1}  
PATCH SYSRES/SYS {R=15 B=145 F=36FFE1 C=C3A71D}  
PATCH SYSRES/SYS {R=30 B=52 F=0000000000000000 C=36FF6069C38A0E}  
PATCH SYSRES/SYS {R=15 B=148 F=C1545D7E23666F C=545D7E23666FC1}
```