

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4512-05
Description	Profile II
Model	Model II
Stock No.	26-4512 Version 1.0
Date	May 21, 1982
Page 1 of	1

Problem

This program requires modifications as described below before it can be FCOPYed for hard disk use.

* * THIS PATCH IS REQUIRED FOR USE ON HARD DISK! * *

Solution

At TRSDOS READY, apply the following patches to correct the above problem.

PATCH CREATE/EFC A=51AE F=34 C=38