

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4705-04 (Correction 1)
<b>Description</b>	RSBASIC Compiler
<b>Model</b>	Model II
<b>Stock No.</b>	26-4705 Version 2.4
<b>Date</b>	Jan. 27, 1982
<b>Page 1 of</b>	1

### **Problem**

Any program compiled under RSBASIC Compiler and operating under RUNBASIC or RUNTIME BASIC can develop a problem when processing ISAM files. This problem will be manifested as an unexpected termination of the program and a return to TRSDOS READY status without displaying any error messages. The problem is caused when RUNBASIC (or RUNTIME BASIC) calls the module, RSBASIC/LIO, which handles the deletion of ISAM records. When deleting a particular group of ISAM records, the module fails to complete the deletion process, which causes RUNBASIC (or RUNTIME BASIC) to fail with a subsequent return to TRSDOS.

\* \* THESE PATCHES ARE REQUIRED! \* \*

### **Solution**

At TRSDOS READY, apply the following patch to correct the problem.

```
PATCH RSBASIC/LIO A=45C2 F=44 C=4A
PATCH RSBASIC/LIO A=45EA F=1C C=22
PATCH RSBASIC/LIO A=45FE F=3654183C C=A26118AD
PATCH RSBASIC/LIO A=4602 F=00C3040A C=1A013654
PATCH RSBASIC/LIO A=4606 F=76241860 C=0E3C00C3
PATCH RSBASIC/LIO A=460A F=1A58A259 C=060A7024
```

#### **\*\*\*\*NOTE\*\*\*\***

If the user has the RUNTIME BASIC disk(26-4706), the above patch should be applied to it also.

This patch should also be applied to KANA versions.