

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No. 4714-03
Description REFORMATTER
Model Model II/12
Stock No. 26-4714 Version 01.5b.00
Date March 12, 1984
Page 1 of 1

Problem

On TRSDOS to IBM transfer, if last record on IBM diskette is in sector 26, the data set label will not be correctly updated.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

At TRSDOS READY, apply the following PATCHES to a BACKUP copy of REFORMATTER.

PATCH REFM A=461E F=FA5A C=5546

PATCH REFM A=2A01 F=62 C=63

After the PATCHES from this bulletin have been applied the Version number will be 01.5c.00. Please make the necessary entry in your Version Log.