

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	6105-09
Description	TRSDOS 16
Model	Model II/16
Stock No.	26-6105 Version 4.1
Date	September 30, 1982
Page 1 of	1

Problem

The distribution version of the SAVE utility on TRSDOS 4.1 does not properly handle diskettes with flawed sectors. Upon reaching a flawed sector, the program performs an infinite number of attempts to write to that sector.

The following patch corrects the situation to allow the SAVE utility to handle flawed diskettes.

* * THE FOLLOWING PATCH IS REQUIRED! * *

Solution

1. At TRSDOS Ready, apply the following patch.

```
PATCH SAVE R=18 B=119 F=CDCF39DD360102C5 C=C5CDCF39DD360102
```

2. Make a backup copy of the corrected diskette.