



# Radio Shack

A Division of Tandy Corporation

NORTHEAST REGION  
U.S.A. FRANCHISE / DEALER DIVISION 617-963-8100

10 MAZZEO DRIVE, SUITE 201, RANDOLPH, MA 02368

TO : ALL DEALER/FRANCHISEES  
FROM : HOWARD M. GLASSMAN, COMPUTER MARKETING SPECIALIST  
DATE : AUGUST 20, 1982  
SUBJECT : TRSDOS 2.0b PATCHES

Due to a potential timing problem, the THINLINE and UNTHIN patches will have to be changed. Please perform the following Patches:

```
PATCH THINLINE R=379 B=1 F='1' C='2'  
PATCH THINLINE R=380 B=1 F='9' C='5'  
PATCH UNTHIN R=379 B=1 F='1' C='2'  
PATCH UNTHIN R=380 B=1 F='9' C='5'
```

TRSDOS 2.0b diskettes will also have to be patched so that they will have the proper wait. To do so, perform the following Patch:

```
PATCH SYSRES/SYS A=1EF9 F=19 C=25
```

It is **VERY IMPORTANT** that any SCRIPSIT disk used in a Model 16 have these patches.

To correct the erroneous operator prompting for "Drive not Ready" when running FORMAT (either from within SCRIPSIT or from "TRSDOS READY"), apply the following patches to the FORMAT utility:

```
PATCH FORMAT A=34C8 F=CD962DCD182D C=CDAF35000000  
PATCH FORMAT A=352F F=FE51CA7828FE5920EC C=FE59C2782800CDAF35  
PATCH FORMAT A=35AF F=284D6F756E7420446973 C=CD962D474FCD322DCD32  
PATCH FORMAT A=35B9 F=6B6574746520666F7220 C=2DCD182DC9194D6F756E  
PATCH FORMAT A=35C3 F=466F726D617474696E67 C=74204469736B20746F20  
PATCH FORMAT A=35CD F=206F6E204472697665 C=466F726D6174206F6E  
PATCH FORMAT A=2830 F=AF C=BE  
PATCH FORMAT A=350A F=2D C=29  
PATCH FORMAT A=3511 F=26 C=22  
PATCH FORMAT A=351D F=1A C=16  
PATCH FORMAT A=3523 F=14 C=10
```

NOTE: The DO-file of patches for TRSDOS 2.0b for the new thin-line disk drives ("THINLINE") must be installed prior to the installation of the above patches. These patches are not valid for TRSDOS 2.0a.

Should you have any additional questions, please feel free to contact me at the Regional Office.