

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4705-01
Description	Basic Compiler
Model	Model II
Stock No.	26-4705 Version 2.4
Date	December 6, 1981
Page 1 of	1

### Problem

In some cases, calculating the record length and the number of records in a file, it is possible not to find a record that is actually in the file. The problem has been reported as OPENING two Binary files and two ISAM files at the same time. An OVERFLOW error persists regardless of the stack size or record length. Another manifestation of the problem is OPENING, WRITING, and CLOSING alternately between two ISAM files. In this case, another form of the error will occur after several records have been written.

### Solution

To correct the problem, apply the following PATCHes:

```
PATCH RSBASIC/LIO A=3666 F=2024 C=0003
PATCH RSBASIC/LIO A=369B F=0037 C=4256
PATCH RSBASIC/OLF R=92 B=120 F=000000000000 C=DDE1C30956
PATCH RSBASIC/OLF R=155 B=67 F=8B35 C=7756
PATCH RSBASIC/OLF R=155 B=103 F=2024 C=0003
PATCH RSBASIC/OLF R=155 B=156 F=0037 C=4256
```