

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

| | |
|--------------|------------------------------|
| Bulletin No. | <u>4912-04</u> |
| Description | <u>TRSDOS II</u> |
| Model | <u>Model 12/16</u> |
| Stock No. | <u>26-4912 Ver. 04.02.02</u> |
| Date | <u>July 20, 1983</u> |
| Page 1 of | <u>1</u> |

Problem

The write protect message can become scrambled.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

After patches from this Bulletin have been applied, the version number will be 04.02.03. Please make the necessary entry in your Version Log.

PATCH BACKUP:0 R=15 B=28 F=212A39CB77280E3E4FD3EF C=CB77280E3E4FD3EF212A39
PATCH BACKUP:0 R=15 B=43 F=FB C=F8